REPORT OF CHANNEL CONDITIONS						Page 1 of 1		
100 TO 400 FEET WIDE (ER 1130-2-316)							February 2001	
TO: Director, Department of Environmental Resources Management 33 SW 2nd Ave., Miami, FL RIVER/HARBOR NAME AND STATE			USAC Attn: 0	FROM: USACE. District Engineer Attn: CESAJ-CO-OM Jacksonville, Florida MINIMUM DEPTHS IN EACH 1/4 WIDTH OF				
Miami River, Dade County, FL				CHANNEL ENTERING FROM SEAWARD				
NAME OF CHANNEL	Date of Survey	AUTHORI Width	ZED PROJ Length	ECT Depth	Left Outside Quarter	Middle Half	Right Outside Quarter	
	·	(feet)	(miles)	(feet)	(feet)	(feet)	(feet)	
Miami River, Cut-1 thru Cut-9	Jul-2000	150	0.87	15	6.2 (1)	11.0 (1)	8.9 (1)	
Cut-10 thru Cut-15	Jul-2000	150	0.73	15	4.4 (2)	10.9 (2)	10.0 (2)	
Cut-16 thru Cut-23	Jul-2000	150	0.54	15	6.7 (3)	12.1 (3)	9.8 (3)	
Cut-24 thru Cut-29	Jul-2000	150	1	15	5.2 (4)	11.4 (4)	9.3 (4)	
Cut-30 thru Cut-32	Jul-2000	150	0.17	15	9.4 (5)	13.8 (5)	8.1 (5)	
Cut-33 thru Cut-39	Jul-2000	125	0.53	15	6.7 (6)	13.3 (6)	9.3 (6)	
Cut-40 thru Cut-42	Jul-2000	125	0.73	15	8.1 (7)	10.3 (7)	6.9 (7)	
Cut-43 thru Cut-47	Jul-2000	90	0.9	15	7.5 (8)	12.1 (8)	10.1 (8)	
Cut-48 to west end of Federal Project	Jul-2000	90	0.4	15	8.7 (9)	8.1 (9)	5.7 (9)	

## Remarks:

- 1. Shoaling throughout both outside quarters of channel. Least depths occur in the southern side of channel at the P.I. of Cut-1 & 2.
- 2. Shoaling throughout both outside quarters of channel. Least depth occurs in westerly side of channel, near P.I. of Cut-11 & 12. Deepest depths in Cuts-11 & 15 are located in northern side of middle half of channel.
- 3. Shoaling throughout both outside quarters of channel. Deepest depths in Cut-20 are located in northern side of middle half of channel.
- 4. Shoaling throughout both outside quarters of channel. Deepest depths in Cuts-25 thru 29 are located in northern side of middle half of channel.
- 5. Shoaling throughout both outside quarters of channel.
- 6. Shoaling throughout both outside quarters of channel.
- 7. Shoaling throughout both outside quarters of channel. Least depths located approximately 90 feet east of the P.I. Of Cuts-41 & 42.
- 8. Shoaling throughout both outside quarters of channel from Cut-43 thru Cut-46. Shoaling throughout entire channel in Cut-47.
- 9. Shoaling throughout entire reach. Least depths occur toward west end of project.